

## Facility Summary in GRANITE County in the City of DRUMMOND

**Location:** FICS KWIK SIX  
410 E FRONT ST  
DRUMMOND, MT 59832 GRANITE

**Sys Fac ID:** 20-03192

**Last Inspected On:** 8/21/2013

**Operating Permit Renewal Date:** 10/14/2016

**Contact:** Todd Fickler, (406) 846-3970

**Owners/Operators:** Fickler Oil Co Inc Deer Lodge, Owner (406)-846-3970 725 MAVERICK LN  
DEER LODGE MT 59722-2347

Bonnie Cyr, UST Class A Operator  
Judy Rasmussen, UST Class A Operator  
Bonnie Cyr, UST Class B Operator  
Todd Flicker, UST Class B Operator  
Judy Rasmussen, UST Class B Operator  
Dolly Brewer, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	05	7/1/2010	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
<b>5264</b>			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
12,000		11/18/2009			Yes
11	05	7/1/2010	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
<b>5265</b>			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
5,000		11/18/2009			Yes
12	05	7/1/2010	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
<b>5266</b>			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000		11/18/2009			Yes

## Facility Summary in GRANITE County in the City of DRUMMOND

**Location:** FICS KWIK SIX  
410 E FRONT ST  
DRUMMOND, MT 59832 GRANITE

**Sys Fac ID:** 20-03192  
**Last Inspected On:** 8/21/2013  
**Operating Permit Renewal Date:** 10/14/2016

**Contact:** Todd Fickler, (406) 846-3970

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
13	05	7/1/2010	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
<b>5267</b>			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
5,000		11/18/2009			Yes

## Facility Summary in GRANITE County in the City of DRUMMOND

**Location:** MOUNTAIN WEST CO OP  
350 E FRONT ST  
DRUMMOND, MT 59832 GRANITE

**Sys Fac ID:** 20-03611

**Last Inspected On:** 1/20/2016

**Operating Permit Renewal Date:** 1/5/2019

**Contact:** Chuck Thompson, (406) 543-8383

**Owners/Operators:** Mountain West Coop - Drummond, Owner (406)-288-3219 PO BOX 297  
DRUMMOND MT 59832  
John Thompson, Operator (406)-665-1728 209 N MAIN ST  
BRIDGER MT 59014  
John Thompson, UST Class A Operator  
Robin Cochrell, UST Class B Operator  
John Thompson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	55	6/15/1960	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
<b>4461</b>			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		5/25/2015	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		1/19/2016	Gilbarco EMC Basic , Gilbarco		
6	55	6/15/1960	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
<b>1458</b>			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/25/2015	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		1/19/2016	Gilbarco EMC Basic , Gilbarco		
7	44	6/16/1971	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Positive Shutoff
<b>1459</b>			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/25/2015	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		1/19/2016	Gilbarco EMC Basic , Gilbarco		

## Facility Summary in GRANITE County in the City of DRUMMOND

**Location:** MOUNTAIN WEST CO OP  
350 E FRONT ST  
DRUMMOND, MT 59832 GRANITE

**Sys Fac ID:** 20-03611

**Last Inspected On:** 1/20/2016

**Operating Permit Renewal Date:** 1/5/2019

**Contact:** Chuck Thompson, (406) 543-8383

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	24	5/13/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
<b>1460</b>			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		5/25/2015	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		1/19/2016	Gilbarco EMC Basic , Gilbarco		
9	24	5/13/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
<b>1461</b>			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		5/25/2015	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		1/19/2016	Gilbarco EMC Basic , Gilbarco		

## Facility Summary in GRANITE County in the City of PHILIPSBURG

**Location:** SUNSHINE STATION 417  
3830 MT HIGHWAY 1  
PHILIPSBURG, MT 59858 GRANITE

**Contact:** Bob Derosia, (406) 859-3450

**Sys Fac ID:** 20-05771  
**Last Inspected On:** 11/14/2014  
**Operating Permit Renewal Date:** 2/11/2018

**Owners/Operators:** Hi Noon Petroleum Missoula, Owner (406)-532-0381 PO BOX 7578  
MISSOULA MT 59807-7578

Randy Livingston, UST Class A Operator  
Keith Dowling, UST Class B Operator  
Bill Dirkes, UST Class B Global Operator  
Randy Livingston, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	32	4/27/1983	Bare Steel	Flexible Plastic	High Level Alarm
1313			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/26/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000					
2	32	4/27/1983	Bare Steel	Flexible Plastic	High Level Alarm
4516			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/26/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000					
3	16	9/20/1999	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4517			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		2/26/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
12,000					

## Facility Summary in GRANITE County in the City of PHILIPSBURG

**Location:** PINTLER PETROLEUM INC  
906 W BROADWAY RD  
PHILIPSBURG, MT 59858 GRANITE

**Sys Fac ID:** 56-13983

**Last Inspected On:** 9/18/2014

**Operating Permit Renewal Date:** 10/7/2017

**Contact:** Bill Antonioli, (406) 859-3164

**Owners/Operators:** William Antonioli, Owner

(406)-859-3164

PO BOX 486

PHILIPSBURG MT 59858-0486

William Antonioli, UST Class A Operator

William Antonioli, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	15	9/1/2000	Unknown	Flexible Plastic	
<b>4215</b>	Yes	9/17/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
12,000					
2	15	9/1/2000	Unknown	Flexible Plastic	
<b>4216</b>	Yes	9/17/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000					
3	15	9/1/2000	Unknown	Flexible Plastic	
<b>4217</b>	Yes	9/17/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
20,000					
4	15	9/1/2000	Unknown	Flexible Plastic	
<b>4218</b>	Yes	9/17/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
24,000					